# Firmware Upgrade Notice

1. Place the updated software file in the empty USB drive, which is to avoid the conflict between the updated software file and other files in the USB drive. The updated software file is the only file that should be on the USB drive.

    There are two updates for these units, an MPEG and an MCU, the MPEG needs to be the first followed by the MCU update. Make sure to unzip the downloaded file and extract the ".img" file, copy to a blank flash drive.

2. During the software upgrading process, please do not remove the USB drive, turn off ACC or cut power to the unit, or operate the unit in any way, FOR THIS WILL PERMANENTLLY DAMAGE THE UNIT and will no longer function.

2. During the upgrading process, the unit will display the status of upgrading and reset once completed (PLEASE BE PATIENT), you may remove the USB and turn off the ACC power to reset the head unit. MPEG UPDATE

(Erase the file from the flash drive and copy the next file onto the drive and continue)

4. After MCU update, the unit will turn off, at this point press the reset button for 10 seconds then restart the unit.(Reset button is the small pin hole on the front face of the unit)

MCU UPDATE